

DAILY INSPECTION REPORT

Tanggal Pemeriksaan : 8 April 2026

Instalasi : Instalasi Hydrant

Pemilik : PT MULTI SPUNINDO JAYA Tbk

Lokasi : Gedung B, C dan E

No.	Pictures	Descriptions	Findings	Recommendations	Follow-Up	HC*
1.	   	Pemeriksaan visual pada sistem pompa hydrant : - Pompa pacu (Jockey pump) - Pompa cadangan (diesel pump) - Pipa hisap, valve dan pressure gauge - Bejana tekan - Pressure switch - Pressure relief valve - Centrifugal pump	Terdapat rembesan/kebocoran pada centrifugal diesel pump	Lakukan perbaikan pada centrifugal pump yang merembes/bocor	-	B
2.	 	Pemeriksaan visual pada Outdoor Hydrant Box : - Kunci box - Nozzle - Hydrant valve - Rubber hose - Rak - Cat	Kondisi baik	-	-	

No.	Pictures	Descriptions	Findings	Recommendations	Follow-Up	HC*																				
3.	 	Pemeriksaan visual pada Indoor hydrant box : - Kunci box - Nozzle - Hydrant valve - Rubber hose - Rak - Cat	-	-	-	-																				
4.		Pengujian operasioanal pompa: <table><tr><th>Pompa</th><th>Start</th><th>Stop</th><th>Keterangan</th></tr><tr><td>Pompa pacu</td><td>Auto 6 Kg/cm²</td><td>Auto / manual 8 Kg/cm²</td><td>-</td></tr><tr><td>Pompa utama</td><td>-</td><td>-</td><td>-</td></tr><tr><td>Pompa cadangan</td><td>Auto 4 Kg/cm²</td><td>Manual - Kg/cm²</td><td>-</td></tr></table>					Pompa	Start	Stop	Keterangan	Pompa pacu	Auto 6 Kg/cm ²	Auto / manual 8 Kg/cm ²	-	Pompa utama	-	-	-	Pompa cadangan	Auto 4 Kg/cm ²	Manual - Kg/cm ²	-				
Pompa	Start	Stop	Keterangan																							
Pompa pacu	Auto 6 Kg/cm ²	Auto / manual 8 Kg/cm ²	-																							
Pompa utama	-	-	-																							
Pompa cadangan	Auto 4 Kg/cm ²	Manual - Kg/cm ²	-																							
5.	   	Pengujian operasioanal instalasi hydrant kebakaran: <table><tr><th>No.</th><th>Percobaan</th><th>Tekanan</th><th>Status</th><th>Keterangan</th></tr><tr><td>1.</td><td>Tekanan Stand by</td><td>8 Kg/cm²</td><td>Baik</td><td>Memenuhi</td></tr><tr><td>2.</td><td>1 titik hydrant box</td><td>7 Kg/cm²</td><td>Baik</td><td>Hydrant box terdekat</td></tr><tr><td>3.</td><td>2 titik hydrant box</td><td>5 Kg/cm²</td><td>Baik</td><td>Hydrant box terjauh dibuka secara bersamaan</td></tr></table>					No.	Percobaan	Tekanan	Status	Keterangan	1.	Tekanan Stand by	8 Kg/cm ²	Baik	Memenuhi	2.	1 titik hydrant box	7 Kg/cm ²	Baik	Hydrant box terdekat	3.	2 titik hydrant box	5 Kg/cm ²	Baik	Hydrant box terjauh dibuka secara bersamaan
No.	Percobaan	Tekanan	Status	Keterangan																						
1.	Tekanan Stand by	8 Kg/cm ²	Baik	Memenuhi																						
2.	1 titik hydrant box	7 Kg/cm ²	Baik	Hydrant box terdekat																						
3.	2 titik hydrant box	5 Kg/cm ²	Baik	Hydrant box terjauh dibuka secara bersamaan																						

No.	Pictures	Descriptions	Findings	Recommendations	Follow-Up	HC*
6.		Pemeriksaan visual pada siameese connection (sambungan pemadam kebakaran)	Instalasi hydrant siameese connection dalam kondisi baik	-	-	-

Keterangan :

HC * (Hazard Classification)

A : a condition or practice likely to cause permanent disability, loss of life or body part, and/ or extensive loss of structure, equipment or material

B : a condition or practice likely to cause serious injury or illness, resulting in temporary disability or property damage that is disruptive but not extensive

C : a condition or practice likely to cause minor, non-disabling injury or illness, or non-disruptive property damage

Kesimpulan:

- Dari hasil pemeriksaan dan pengujian yang telah dilakukan, dapat disimpulkan bahwa pada Instalasi Hydrant tersebut memenuhi syarat Keselamatan dan Kesehatan Kerja dengan memperhatikan dan segera menindaklanjuti saran-saran yang diberikan.

Sidoarjo, 8 April 2026

Dilakukan oleh

PT ADIKA ATMAJA TEKNIK

Mengetahui :

PT MULTI SPUNINDO JAYA Tbk

Farid Nur Hamzah

Inspector
